

Republic of the Philippines  
Province of Bohol  
Municipality of Jagna  
OFFICE OF THE MUNICIPAL ENGINEER

POST DAMAGE ASSESSMENT REPORT DURING TYPHOON QUEENIE NOV.26, 2014-11-20

	Name/ Address	No.of Families	Extent of Damages	Remarks
	Barangay Looc		All of these are situated along the shorelines,	
1.	Mr.Rosaleo Ortiz	4	a) The 1½ storey residential house of Mr.& Mrs. Rosaleo Ortiz was situated along shore line of Barangay Looc, It was made of mixed materials concrete & wood .The walling of the living room facing seaside is made of ¼" thick clear glass and one side of the bedroom facing seaside the walling was made also of clear glass was totally damaged/broken.The dirty kitchen made of wood and bamboo ,was totally wrecked .There are also cracks on the flooring .The riprap serves a a seawall was also damaged.	The owner was still occupying at the at the elevated portion of the building.
			b) The appliances like Refregerator, t.v. set, kitchen wares was also damaged. Per interview of the owner ,dead body was found in the bedroom were it was damaged.	Assessed Dec. 2, 2014
2.	Salustiano Virtudes Jr. (reported as Ebbie Ranin)	1 male	a) The old two storey residential house of Salustiano Virtudez Jr was made of mixed materials . Flooring at the living room is concrete while in the bedroom is of wooden flooring. The ground floor was totally damaged and the stairway to second floor was partially damaged, but second floor was of wooden materials is still intact.	The owner still occupying but making a makeshift enough for him.
			b) The concrete perimeter fence at left side and at the back portion was totally collapsed and so with the riprap serves as seawall was also damaged	Assessed Dec. 2, 2104.
3.	Felicitas /Labrador Galagar	5	a) The old wooden house was totally damaged ,the persons occupying moved to West Ulbujan, Garcia Hernandez Bohol, the place of their daughter in law.	Assessed Dec. 2, 2014
4.	Elisia/Teofesto Baja	2	a) The old amakan house was totally damaged. The occupants of the is the son of the owner, moved to Barangay Victoria, Garcia Hernandez, Bohol( house was lying on the ground,nahapla)	Assessed Dec. 2, 2014
5.	Oscar Magdayo		a) Nipa house with bamboo flooring, totally damaged.	
6.	Virginia Acedo (owner)as reported Paul Ranara	3	a) 3 rooms rented by 3 families made coco lumber,amakan walling, G.I.sheets ,concrete flooring, Only concrete CR left ,main building washed out.	
7.	Allan Cespon	1	b) The house was made of amakan,coco and combination of g,i sheets and nipa, was totally washed out	
8.	Paguican, Lucilo	1	a) Nipa house totally washed out, 10' x 12'	Living in his mother's house
4.	Galigo, Asuncion		a) Rented Christopher Sajulga made nipa ,coco lumber and amakan walling , washed out.	(1/3)
5.	Clirio Oconeja	1	a) Concrete house ,trusses and roofing blown away, totally damaged (22' x 20')	Leaving with mother-in-law
6.	Yanez Lloven	1	a) Made of light materials with g,i sheets as roofing, blown away, totally damaged.	
7.	Asilo Rene	1	a) Only terrace was damaged	
8.	Despolo, Henry	1		



BARANGAY BUNGA MAR		Republic of the Philippines Province of Bohol Municipality of Jagna OFFICE OF THE MUNICIPAL ENGINEER	
1.	Alero Gumerindo		a) Nipa hut totally washed out
2.	Ladaga, Lucio		a) Nipa hut totally washed out
3.	Sajol, Anatolio	1	a) Walling damaged, living room no where to be found, might be buried
4.	Abulag, Severino	1	a) Damaged
5.	Bongcayo, Rosita	No. of Families	a) Damaged nipa roofing
Name/ Address		Extent of damages	
Barangay Cantagay			
1.	Mrs. Janeth Madera	5	a) The amakan house of Mrs. Janeth Madera was made of 12' x 20' amakan and G.I. sheets was totally washed out typhoon.
Barangay Cantagay			
2.	Virador Honorato	1 male	a) The shop of Virador was made of old shts of G.I. as wallings and roofing ,totally damaged
3.	Eufrefia Alvarez	1	a) Rest house was totally washed out
4.	Nonoy Oclarit	1	b) The old amakan house was totally damaged. (unreported)
Barangay Cantagay			
Barangay Alejawan			
1.	Gomera Bernaldo	1	a) This 10' x 16' house was made of amakan, nipa and coco lumber , completed 2 months from the destructive typhoon quennie, though the owner was already occupying it. It was totally damaged situated 20 m. Away from the the alejawan river bank
2.	Gomera ,Edgar	1	a) This 10' x 14' is still skeleton, made of coco lumber and nipa was totally damaged.
3.	Lipatis, Absalon	1	a) This 10' x 14' made of amakan, coco lumber and nipa was totally damaged,
4.	Carlom, Venancio	1	a) This 10' x 14' made of amakan, coco lumber and nipa was totally damaged
5.	Tadem, Juanito	1	a) Old wooden house half chb and amakan, g.i corrugated shts. as roofing totally damaged
6.	Bolaer Eutiquio	1	a) This was rented by another family ,totally damaged
BARANGAY TUBOD MAR			
1.	Galinato ,Rustico	2	a) The 2 storey Main building was made of mixed materials the roofing facing seaside was blown away ,and kitchen was totally washed out .
2.	Dispolo ,Glenn	2	a) The affected area are roofing of the dining, and kitchen ,T & B and part of Living room, only part of living and bedroom was left.
3.	Galgo, Federico	1	a) Made of CHB and nipa, washed out, totally damaged.
4.	Galgo, Asuncion	1	a) Made of concrete ,dining and kitchen washed out., riprap was scoured.
5.	Cirilo Ocmeja	1	a) Rented Christopher Sajulga made nipa ,coco lumber and amakan walling , washed out.
6.	Yanez, Lloven	1	a) Concrete house ,trusses and roofing blown away, totally damaged (22' x 20')
7.	Asilo Rene	1	a) Made of light materials, with g.i sheets as roofing, blown away, totally damaged.
8.	Despolo, Henry	1	a) Only terrace was damaged.



	BARANGAY BUNGA MAR		
1.	Acero Gumersindo		a) Nipa hut totally washed out (butanganan ug pokot)
2.	Ladaga, Lucio		a) Nipa hut totally washed out (kamalig )
3.	Sajol, Anatolio	1	a) Walling damaged, living room was filled with sand, and appliances no where to be found, might carried by big waves.
4.	Abulag, Severino	1	a) Damaged roofing and walling (3.0 x 3.5 )6 shts. Of G.I roofing)
5.	Bongcayo, Rosita	1	a) Damaged nipa roofing.
	BARANGAY CAN-UPAO		
1.	Forones, Pio	1	a) Two storey nipa house totally damaged (10' x 12')
2.	Forones, Pablo		a) Two storey, amakan, with g.i as roofing, with extension of dining, kitchen, using nipa as roofing totally damaged.
3.	Hipgano, Maxima	1	a) Nipa house, amakan totally damaged (10' x 14')
4.	Hipgano, Armando	1	a) Nipa house, amakan totally damaged (10' x 14')
5.	Garay, Vicente	1	a) Amakan house with G.I. sheets as roofing totally damaged (14' x 22')
6.	Cuadra, Pascual	1	a) Nipa house, amakan totally damaged (12' x 12')
7.	Balanay, Rey	1	a) Nipa house, amakan totally damaged (18' x 20')
	BARANGAY NAATANG		
1.	Baja, Alma		a) Damaged wooden walling facing seaside, some of the roofing was blown away, transfer to Alejawan, Jagna. Totally damaged. (12' x 22')
2.	Aying, Marcial		a) Wooden house, g.i sheets as roofing, totally damaged (nahapla) (18' x 20')
3.	Sajulan, Benjamin		a) 1½ storey vacation house made of CHB with wooden flooring at second floor, only concrete flooring at the ground floor left. Totally damaged

(3)

Prepared by :

Engr. JOSEFINA S. RANO  
Municipal Engineer

Recommending Approval

Engr. GERRY V. ARANETA  
MPDC, Environmental Planner

Approved :

Atty. FORTUNATO R. ABRENILLA  
Municipal Mayor